NOT Ä	ÄNDRING	INFÖRD	SIGN	EXAMPLE SINGLE-LINE DIAGRAM Low voltage switchgear LV Typ	e 5	KONSTR. KJS RIT. KJS KOLL. HRo GODK. SKALA DAT. 2023-10-23	SECONDARY SUBSTATION LV Type 5 SWITCHGEAR Single-line diagram	Attachment 5 ERS. BLAD 1 FORTS.BLAD -
V	0,5 kV Three phase voltage measurement connected to the			8 17 16 15 14 13 12 11	10 9 gency power is á 630A	2000A Pos. T12-0,4-IT Pos. T12-0,4-F 8 7 6 5 4 3 2 Outbound cables, 9 pcs á 400A		→ sign.
		. 1010						
A	Current measurement connected to the RTU							
man.	Maneuver from RTU							
pos.	Double point position of Beraker/Load disconnector							
₹ sign.	Signal/Alarm			1				